

**From:** [Moore, Gary](#)  
**To:** ["Gavlas, Sean"](#)  
**Subject:** F.J. Doyle  
**Date:** Friday, September 28, 2018 10:29:38 AM

---

Recommendation:

Asbestos Assessment: Need quick turnaround on data and quick turnaround on report

Coating/Paint Chip Sample: 1 sample from chips taken from all 4 sides of the building - analytical: asbestos (if potential galbestos), metals (potentially lead), PCBs (potentially galbestos coating w/ PCB – must add Arochlor 1268 to list of Arochlors)

Wipe Samples Building (interior/exterior): approximately 12 plus QA/QC

Drainage Ditches: the ones we talked about use same sample scheme.

Need fairly quick turnaround – 7 days if possible.

**Gary W. Moore (6SF-ER)**  
**Federal On-Scene Coordinator**  
**U.S EPA Region 6**  
**1445 Ross Ave, Suite 1200**  
**Dallas, TX 75202-2733**  
**Cell: 214.789.1627**  
**moore.gary@epa.gov**